

**Illinois Commerce Commission  
Pipeline Safety  
Field Trip Report**

<b>Operator: AMEREN ILLINOIS COMPANY</b>	<b>Operator ID#: 32513</b>
<b>Exit Meeting Contact: Rodger Camerer</b>	<b>Total Man Days: 3</b>
<b>Pipeline Safety Representative(s): Donald Hankins</b>	
<b>Company Representative to Receive Report: Michael Fuller</b>	<b><u>Emailed Date:</u></b>
<b>Company Representative's Email Address: mfuller2@ameren.com</b>	10/22/2013

**Inspection Summary**

<b>Inspection Type</b>	<b>Location</b>	<b>ICC Analyst</b>	<b>Inspection Unit(s)</b>	<b>Man Day(s)</b>	<b>Inspection Date(s)</b>	<b>Contact(s)</b>
Design Testing and Construction	Jacksonville	Donald Hankins	Jacksonville	3	9/3/2013, 9/4/2013, 9/5/2013	Rodger Camerer

**Statement of Activities**

On September-3-5, 2013, a field audit was conducted at Ameren Illinois, in Jacksonville, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

Staff conducted a field audit by inspecting Ameren crews changing isolated steel services at the meter sets. Isolated services were changed at the following locations: 101 Chestnut Street, 337 West Lafayette Avenue, 341 West Lafayette Avenue, and 301 East Greenwood Avenue in Jacksonville, Illinois. The new risers were air tested to the following pressures: 101 Chestnut Street, 104 psig for 16 minutes; 327 & 341 West Lafayette Avenue, 105 psig for 10 minutes; 301 East Greenwood Avenue, 102 psig for 12 minutes; with no leaks being found.

**ISSUE(S) FOUND:**

NO ISSUES FOUND.

**ISSUE(S) CORRECTED:**

NO ISSUES CORRECTED.

**NOTICE OF AMENDMENT(S) FOUND:**

NO NOAs FOUND.

**NOA(S) CORRECTED:**

NO NOAs CORRECTED.

**NOTICE OF PROBABLE VIOLATION(S) FOUND:**

NO NOPVs FOUND.

**NOPV(S) CORRECTED:**

NO NOPVs CORRECTED.